

Release Notes

Public Release

| Version 1.1.0 | |
|---------------|--|
| Features | <ul style="list-style-type: none"> Support for revision C and newer hardware. |
| Bug Fixes | <ul style="list-style-type: none"> Fixed compatibility with Lumens VC-B20D and similar DVI video sources. |
| Known Issues | <ul style="list-style-type: none"> Video loss after disconnect/reconnect of display HDMI cable, when using mode 4: 5V LOCK. <i>Workaround: Use mode 1: LINK</i> |

Previous Releases

| Version 1.0.16 | |
|----------------|--|
| Features | <ul style="list-style-type: none"> N/A |
| Bug Fixes | <ul style="list-style-type: none"> Increased stability when switching inputs while using Marantz SR7013, Anthem MRX-720, and Denon X6500H & S740H AVRs. |
| Known Issues | <ul style="list-style-type: none"> Some video loss and flickering may occur with Integra DRX-5.2, DRX-4.2, and DRX-7.1 AVRs. If problems persist, make sure to upgrade the Integra receiver with the latest firmware. |

| Version 1.0.15 | |
|----------------|---|
| Features | <ul style="list-style-type: none"> N/A |
| Bug Fixes | <ul style="list-style-type: none"> Fixed an issue with Mode 4 (5V Lock), which sets the +5V and the HPD signal of the transmitter and receiver to high. In certain cases, when the display was turned off, the HPD signal would go low, which is what Mode 4 is designed to prevent. |
| Known Issues | <ul style="list-style-type: none"> N/A |

| Version 1.0.14 | |
|----------------|--|
| Features | <ul style="list-style-type: none"> N/A |
| Bug Fixes | <ul style="list-style-type: none"> Fixed an issue where Dolby Vision content would display the incorrect color space when connected to a Sony X900F display. Video sync issue addressed: In rare cases, repeated input switching would result in audio, but no video, when the extender was connected to an AV switch. |
| Known Issues | <ul style="list-style-type: none"> N/A |

| Version 1.0.12 | |
|----------------|--|
| Features | <ul style="list-style-type: none"> N/A |
| Bug Fixes | <ul style="list-style-type: none"> Increased compatibility with non-Atlona extenders. |
| Known Issues | <ul style="list-style-type: none"> N/A |

| Version 1.0.11 | |
|----------------|--|
| Features | <ul style="list-style-type: none"> N/A |
| Bug Fixes | <ul style="list-style-type: none"> Fixed an issue where the DirecTV C61K-700 would detect the sink device as non-4K device when the extender kit is rebooted, or if a loss of signal occurred. Fixed an issue where “green banding” would be displayed on HDMI video, with certain sources such as DirecTV HR54-700 (firmware release 0x1104). Fixed an issue where HDCP “snow” would occur during channel changes when using the DirecTV C61K-700. |
| Known Issues | <ul style="list-style-type: none"> N/A |

Release Notes

Version 1.0.07

| | |
|--------------|---|
| Features | <ul style="list-style-type: none">• N/A |
| Bug Fixes | <ul style="list-style-type: none">• Resolved an issue which resulted in a “snowy” picture or signal loss, when using a DirecTV 4K source.• Resolved incompatibility issue with Dolby Vision 4K @ 30 Hz on several types of displays. |
| Known Issues | <ul style="list-style-type: none">• N/A |

Version 1

- Factory Firmware