

## Release Notes

### Public Release

| Version 1.1.20 |  |
|----------------|--|
| Features       | <ul style="list-style-type: none"> <li>Added support for hardware revision D.</li> </ul>   |
| Bug Fixes      | <ul style="list-style-type: none"> <li>Addressed an issue that prevented the GAIN-120 from being updated using AMS.<br/> <i>Note: firmware prior to 1.1.20 will need to be updated directly using the web pages. Once updated to 1.1.20, future updates via AMS will be possible.</i></li> </ul> |
| Known Issues   | <ul style="list-style-type: none"> <li>In some cases the Hibernation and Analog Signal Detection settings will not be shown in the web UI.</li> </ul>  |

### Previous Releases

| Version 1.0.18 |  |
|----------------|--|
| Features       | <ul style="list-style-type: none"> <li>Added the ability to detect the hardware revision, and will display the Signal Detect option in the web interface, if hardware revision B is detected. Otherwise this feature is hidden for hardware revision A.</li> </ul>                   |
| Bug Fixes      | <ul style="list-style-type: none"> <li>The unit uptime is now reported correctly.</li> <li>Fixed an issue where multiple Telnet sessions were not permitted.</li> <li>Fixed an issue where the unit would not boot correctly, resulting in audio not heard on the output.</li> </ul> |
| Known Issues   | <ul style="list-style-type: none"> <li>None</li> </ul>   |

| Version 1.0.17 |  |
|----------------|--|
| Features       | <ul style="list-style-type: none"> <li>N/A</li> </ul>  |
| Bug Fixes      | <ul style="list-style-type: none"> <li>Fixed an issue where the unit would not power up from standby mode.</li> </ul>  |
| Known Issues   | <ul style="list-style-type: none"> <li>When using multiple Telnet session, the initial session will not receive feedback, even though the API commands will be executed by the device that is being controlled.</li> </ul> |

| Version 1.0.14 |   |
|----------------|---|
| Features       | <ul style="list-style-type: none"> <li>Added the <code>system sta</code> API command.</li> </ul>  |
| Bug Fixes      | <ul style="list-style-type: none"> <li>Updated the Atlona logo on the login screen.</li> <li>Resolved inconsistent Telnet timeout.</li> <li>Fixed an issue where the Telnet timeout interval was reset to its original value after another command was executed.</li> <li>Improved Telnet response on initial connection.</li> <li>Resolved an issue where the Telnet session crashed when connecting to Velocity.</li> </ul> |
| Known Issues   | <ul style="list-style-type: none"> <li>None</li> </ul>  |

| Version 1.0.01 |   |
|----------------|---|
| Features       | <ul style="list-style-type: none"> <li>N/A</li> </ul>   |
| Bug Fixes      | <ul style="list-style-type: none"> <li>System stability improvements for polling when used with Atlona Velocity™ or other third-party control.</li> </ul> |
| Known Issues   | <ul style="list-style-type: none"> <li>N/A</li> </ul>   |

| Version 1 |  |
|-----------|--|
|           | <ul style="list-style-type: none"> <li>Factory Firmware</li> </ul> |