

## Release Notes

---

### Public Release



**IMPORTANT:** The 1.2.2 firmware is applied to both the MCU and Valens chipset. Since both chips are being updated, the update process can take anywhere from 5 to 10 minutes. Do not power off the system until the firmware update process is complete.

#### Version 1.2.2

Features	<ul style="list-style-type: none"><li>• None</li></ul>
Bug Fixes	<ul style="list-style-type: none"><li>• Update to Valens Firmware 7.5.4.</li><li>• Resolved an issue where cascading USB connections over HDBaseT would cause USB to fail.</li><li>• Fixed a USB-C compatibility issue where no image would be displayed when connect to the system. Resolved compatibility issues with the following devices:<ul style="list-style-type: none"><li>» HP EliteBook</li><li>» HP Chromebook 360</li><li>» Fujitsu Lifebook</li></ul></li></ul>
Known Issues	<ul style="list-style-type: none"><li>• None</li></ul>

### Previous Releases

#### Version 1.2.1

- Factory firmware