

## Release Notes

---

### Public Release

Version 1.1.1	
Features	<ul style="list-style-type: none"> <li>• Error monitoring tool added.</li> <li>• API Mode has additional logging.</li> <li>• Firmware version is now displayed on the e-ink QR home page.</li> </ul>
Function Changes	<ul style="list-style-type: none"> <li>• Macros are limited to 250 items</li> </ul>
Bug Fixes	<ul style="list-style-type: none"> <li>• Button one LEDs now work as intended in test mode.</li> <li>• Passcode now works as intended.</li> <li>• E-ink display no longer displays a grey screen on reboot.</li> <li>• AT-VKP-8E no longer has errors when controlling AT-OME-CS31 through RS-232.</li> </ul>
Known Issues	<ul style="list-style-type: none"> <li>• N/A</li> </ul>

### Previous Releases

Version 1.1.0	
Features	<ul style="list-style-type: none"> <li>• Local Mode:               <ul style="list-style-type: none"> <li>- Background updated</li> <li>- Timeout status is now available on the local webUI</li> <li>- Timeout can now be reset to 20 minutes within the local webUI</li> </ul> </li> <li>• Configuration file can now be downloaded in Local Mode</li> </ul>
Function Changes	<ul style="list-style-type: none"> <li>• Gateway Mode changed to API mode.</li> </ul>
Bug Fixes	<ul style="list-style-type: none"> <li>• N/A</li> </ul>

Version 1	
	<ul style="list-style-type: none"> <li>• Factory Firmware</li> </ul>