

Release Notes ~ AT-HDVS-RX

Public Release

Version 2.2.26

- Fixed error resulting in the command “WP_AutoSwitch[Off]” not being sent

Previous Releases:

Version 2.2.25

- Resolved lockup issue with certain displays and codecs
e.g. Cisco & Lifesize codecs

Version 2.1.0

- Factory Firmware

Public Release

Version 1.1.26

- Fixed error resulting in the command “WP_AutoSwitch[Off]” not being sent

Previous Releases:

Version 1.1.25

- Resolved lockup issue with certain displays and codecs
e.g. Cisco & Lifesize codecs

Version 1.1.0

- Updated HDCP for Apple PCs
- Added internal EDID configurations for better compatibility
- Auto ON/OFF commands for display when an HDMI source is detected
- Added HDCP toggle
(set to compliant, non-compliant, and auto)

Version 1.0.1

- Fixed a bug causing programming errors to erase any characters entered after 00 and 20
- Fixed an error that when the command 5D was entered and processed, the 5D would disappear and the previous data would take its place

Version 1

- Factory Firmware